



ЛЭПКОС

ГК ФЕРРИТ-ХОЛДИНГ

## Аналоги пленочных конденсаторов EPCOS-TDK

| код заказа Ersos (TDK) | код заказа Faratronic → | код заказа JB →     | код заказа Topmay →  | код заказа HUASING |
|------------------------|-------------------------|---------------------|----------------------|--------------------|
| B32652A0104J000        | C323A104J60 →           | JFMAA3104J150000B → | TMCF17-104K1KVP15B → |                    |
| B32652A6104J000        | C322J104J60 →           | JFMA2J104K150000B → |                      |                    |
| B32652A6104K000        | C322J104K60 →           | JFMA2J104J150000B → |                      |                    |
| B32652A0473J000        | C323A473J60 →           | JFMAA3473J150000B → |                      |                    |
| B32652A3224J000        | C322E224J60 →           | JFMA2E224J150000B → | TMCF17-224K250VP15B  |                    |
| B32652A4224J000        | C322G224J60 →           | JFMA2G224J150000B → |                      |                    |
| B32653A0104J000        | C323A104K90C450 →       | JFM02J104K225000B → |                      |                    |
| B32653A2153J000        | C823D153J90C000 →       | JFMA3D153J225000B → |                      |                    |
| B32653A4334J000        | C322G334J90 →           | JFMA2G334J225000B → |                      |                    |
| B32653A6474J000        |                         | JFMA2J474J225000B → |                      |                    |
| B32653A4684J000        | C322G684J90 →           | JFMA2G684J225000B → |                      |                    |
| B32654A0334J000        |                         | JFMAA3334J275000B → |                      |                    |
| B32654A0474J000        |                         | JFMAA3474J275000B → |                      |                    |
| B32654A1104J000        |                         | JFMA3C104J275000B → |                      |                    |
| B32654A6105J000        | C322J105JB0C450 →       | JFMA2J105J275000B → |                      |                    |

|                 |                   |                     |  |  |
|-----------------|-------------------|---------------------|--|--|
| B32654A6684J000 |                   | JFMA2J684J275000B → |  |  |
| B32521C0335J000 | C231J335J4S →     | JFD01J335J100000B → |  |  |
| B32521C3154J000 | C232E154J4S →     | JFD02E154J100000B → |  |  |
| B32522C0106J000 | C231J106J6S →     | JFD01J106J150000B → |  |  |
| B32522C1475J000 | C232A475J6S →     | JFD02A475J150000B → |  |  |
| B32522C3474J000 | C232E474J6S →     | JFD02E474J150000B → |  |  |
| B32522Q8104J000 | C232J104J6S →     | JFD02J104J150000B → |  |  |
| B32523Q4475J000 | C231J475J9S →     | JFD01J475J225000B → |  |  |
| B32524Q3106J000 | C232E106JBS →     | JFD02E106J275000B → |  |  |
| B32524Q8105J000 | C232E105JBS →     | JFD02J105J275000B → |  |  |
| B32529C0104J000 | C241J104J2S →     | JFJ01J104J050000B → |  |  |
| B32529C0105J000 | C241J105J2S →     | JFJ01J105J050000B → |  |  |
| B32529C1103J000 | C242A103J2S →     | JFJ02A103J050000B → |  |  |
| B32529C3103J000 | C242E103J20C450 → | JFJ02E103J050000B → |  |  |
| B32529C3154J000 | C242G154J2S →     | JFJ02E154J050000B → |  |  |
| B32529C6222J000 | C242G222J2S       | JFJ02G222J050000B → |  |  |

|                 |                   |                     |                        |  |
|-----------------|-------------------|---------------------|------------------------|--|
| B32921C3104K000 | C42Q2104K4S →     | JFW0A9104K100000B → | TMCF18-104K305VP10     |  |
| B32921C3223K000 | C42Q2223K40 →     | JFW0A9223K100000B → | TMCF18-223K305VP10     |  |
| B32921C3473K000 | C42Q2473K4S →     | JFW0A9473K100000B → | TMCF18-473K305VP10     |  |
| B32922C3104K000 | C42Q2104K6S →     | JFW0A9104K150000B → | TMCF18-104K305VP15 →   |  |
| B32922C3474K000 | C42Q2474M6SC350 → | JFW0A9474K150000B → | TMCF18-474K305VP15 →   |  |
| B32922C3683K000 | C42Q2683K6A →     | JFW0A9683K150000B → | TMCF18-683K305VP15     |  |
| B32923C3474K000 | C42Q2474K9S →     | JFW0A9474K225000B → | TMCF18-474K305VP22.5 → |  |
| B32923C3105K000 | C42Q2105K9S →     | JFW0A9105K225000B → | TMCF18-105K305VP22.5 → |  |
| B32923C3225K000 | C42Q2225K9S →     | JFW0A9225K225000B → | TMCF18-225K305VP22.5   |  |
| B32924C3105K000 | C42Q2105KBS →     | JFW0A9105K275000B → | TMCF18-105K305VP27.5   |  |
| B32924C3155K000 | C42Q2155KBS →     | JFW0A9155K275000B → | TMCF18-155K305VP27.5   |  |
| B32924C3225K000 | C42Q2225MBSC350 → | JFW0A9225K275000B → | TMCF18-225K305VP27.5   |  |
| B32926C3335K000 | C42Q2335KFS →     | JFW0A9335K375000B → | TMCF18-335K305VP37.5   |  |
| B32926C3685K000 | C42Q2685KFS →     | JFW0A9685K375000B → | TMCF18-685K305VP37.5   |  |
| B32926C3106K000 | C42Q2106KFS →     | JFW0A9106K375000B → | TMCF18-106K305VP37.5   |  |
| B32021A3152K000 | C43Q1152K40 →     | JFYA2152K100000B →  |                        |  |
| B32021A3222K000 | C43Q1222K40C350 → | JFYA2222K100000B →  | TMCF29-222K300VP10B    |  |

|                 |                   |                     |                       |  |
|-----------------|-------------------|---------------------|-----------------------|--|
| B32021A3472K000 | C43Q1472K40 →     | JFYA2472K100000B →  |                       |  |
| B32021A3682K000 | C43Q1682K40 →     | JFYA2682K100000B →  |                       |  |
| B32022A3223K000 | C43Q1223M6SC350 → | JFYA2223K150000B →  | TMCF29-223K300VP15B → |  |
| B32022A3333K000 | C43Q1333K6S →     | JFYA2333K150000B →  |                       |  |
| B32023A3104K000 | C43Q1104K9S →     | JFYA2104K225000B →  |                       |  |
| B32023A3154K000 | C43Q1154K9S →     | JFYA2154K225000B →  |                       |  |
| B32024A3224K000 | C43Q1224KBS →     | JFYA2224K275000B →  |                       |  |
| B32652A0104K000 | C323A104K61C450 → | JFMAA3104K150000B → | TMCF17-104K1KVP15B →  |  |
| B32652A0473K000 | C323A473K60 →     | JFMAA3473K150000B → |                       |  |
| B32652A3224K000 | C322E224K60 →     | JFMA2E224K150000B → | TMCF17-224K250VP15B   |  |
| B32652A4224K000 | C322G224K60 →     | JFMA2G224K150000B → |                       |  |
| B32653A0104K000 | C323A104K90C450 → | JFM02J104K225000B → |                       |  |
| B32653A2153K000 | C823D153J90C000 → | JFMA3D153K225000B → |                       |  |
| B32653A4334K000 | C322G334K90 →     | JFMA2G334K225000B → |                       |  |
| B32653A6474K000 |                   | JFMA2J474K225000B → |                       |  |
| B32653A4684K000 | C322G684K90 →     | JFMA2G684K225000B → |                       |  |

|                 |                   |                     |  |  |
|-----------------|-------------------|---------------------|--|--|
| B32654A0334K000 |                   | JFMAA3334K275000B → |  |  |
| B32654A0474K000 |                   | JFMAA3474K275000B → |  |  |
| B32654A1104K000 |                   | JFMA3C104K275000B → |  |  |
| B32654A6105K000 | C322J105JB0C450 → | JFM02J105K275000B → |  |  |
| B32654A6684K000 |                   | JFMA2J684K275000B → |  |  |
| B32521C0335K000 | C231J335K4S →     | JFD01J335K100000B → |  |  |
| B32521C3154K000 | C232E154K4S →     | JFD02E154K100000B → |  |  |
| B32522C0106K000 | C231J106K6S →     | JFD01K106K150000B → |  |  |
| B32522C1475K000 | C232A475K6S →     | JFD02A475K150000B → |  |  |
| B32522C3474K000 | C232E474K6S →     | JFD02E474K150000B → |  |  |
| B32522Q8104K000 | C232J104K6S →     | JFD02K104K150000B → |  |  |
| B32523Q4475K000 | C231K475K9S →     | JFD01J475K225000B → |  |  |
| B32524Q3106K000 | C232E106KBS →     | JFD02E106K275000B → |  |  |
| B32524Q8105K000 | C232E105KBS →     | JFD02K105K275000B → |  |  |
| B32529C0104K000 | C241J104K2S →     | JFJ01K104K050000B → |  |  |
| B32529C0105K000 | C241J105K2S →     | JFJ01K105K050000B → |  |  |
| B32529C1103K000 | C242A103K2S →     | JFJ02A103K050000B → |  |  |

|                 |                   |                     |                        |                 |
|-----------------|-------------------|---------------------|------------------------|-----------------|
| B32529C3103K000 | C242E103J20C450 → | JFJ02E103K050000B → |                        |                 |
| B32529C3154K000 | C242G154K2S →     | JFJ02E154K050000B → |                        |                 |
| B32529C6222K000 | C242G222K2S →     | JFJ02G222K050000B → |                        |                 |
| B32921C3104M000 | C42Q2104M4S →     | JFW0A9104M100000B → | TMCF18-104K305VP10     |                 |
| B32921C3223M000 | C42Q2223M40 →     | JFW0A9223M100000B → | TMCF18-223K305VP10     |                 |
| B32921C3473M000 | C42Q2473M4S →     | JFW0A9473M100000B → | TMCF18-473K305VP10     |                 |
| B32922C3104M000 | C42Q2104M6SC350 → | JFW0A9104M150000B → | TMCF18-104K305VP15     | C42Q2104M6SC350 |
| B32922C3474M000 | C42Q2474M6SC350 → | JFW0A9474M150000B → | TMCF18-474K305VP15 →   |                 |
| B32922C3683M000 | C42Q2683M6A →     | JFW0A9683M150000B → | TMCF18-683K305VP15     |                 |
| B32923C3474M000 | C42Q2474M9S →     | JFW0A9474M225000B → | TMCF18-474K305VP22.5 → |                 |
| B32923C3105M000 | C42Q2105M9S →     | JFW0A9105M225000B → | TMCF18-105K305VP22.5 → |                 |
| B32923C3225M000 | C42Q2225M9S →     | JFW0A9225M225000B → | TMCF18-225K305VP22.5   |                 |
| B32924C3105M000 | C42Q2105MBS →     | JFW0A9105M275000B → | TMCF18-105K305VP27.5   |                 |
| B32924C3155M000 | C42Q2155MBS →     | JFW0A9155M275000B → | TMCF18-155K305VP27.5   |                 |
| B32924C3225M000 | C42Q2225MBSC350 → | JFW0A9225M275000B → | TMCF18-225K305VP27.5   |                 |
| B32926C3335M000 | C42Q2335MFS →     | JFW0A9335M375000B → | TMCF18-335K305VP37.5   |                 |

|                 |                   |                     |                       |  |
|-----------------|-------------------|---------------------|-----------------------|--|
| B32926C3685M000 | C42Q2685MFS →     | JFW0A9685M375000B → | TMCF18-685K305VP37.5  |  |
| B32926C3106M000 | C42Q2106MFS →     | JFW0A9106M375000B → | TMCF18-106K305VP37.5  |  |
| B32021A3152M000 | C43Q1152M40 →     | JFYA2152M100000B →  |                       |  |
| B32021A3222M000 | C43Q1222M40C350 → | JFYA2222M100000B →  | TMCF29-222K300VP10B   |  |
| B32021A3472M000 | C43Q1472M40 →     | JFYA2472M100000B →  |                       |  |
| B32021A3682M000 | C43Q1682M40 →     | JFYA2682M100000B →  |                       |  |
| B32022A3223M000 | C43Q1223M6SC350 → | JFYA2223M150000B →  | TMCF29-223K300VP15B → |  |
| B32022A3333M000 | C43Q1333M6S →     | JFYA2333M150000B →  |                       |  |
| B32023A3104M000 | C43Q1104M9S →     | JFYA2104M225000B →  |                       |  |
| B32023A3154M000 | C43Q1154M9S →     | JFYA2154M225000B →  |                       |  |
| B32024A3224M000 | C43Q1224MBS →     | JFYA2224M275000B →  |                       |  |
| B32652A0223K000 |                   | JFMAA3223K150000B → |                       |  |
| B32652A0223J000 |                   | JFMAA3223J150000B → |                       |  |
| B32653A4474J000 | C322G474J90 →     | JFMA2G474J225000B → |                       |  |
| B32653A4474K000 | C322G474K90 →     | JFMA2G474K225000B → |                       |  |
| B32654A0684J000 |                   | JFMAA3684J275000B → |                       |  |





































|                 |                   |                     |                         |  |
|-----------------|-------------------|---------------------|-------------------------|--|
| B32654A0684K000 |                   | JFMAA3684K275000B → |                         |  |
| B32654A6155K000 |                   | JFMA2J155K275000B → | TMCF17-155K630VP27.5B → |  |
| B32654A6155J000 |                   | JFMA2J155J275000B → | TMCF17-155J630VP27.5B → |  |
| B32654A7104K000 |                   | JFMA3B104K275000B → |                         |  |
| B32654A7104J000 |                   | JFMA3B104J275000B → |                         |  |
| B32654A4225K000 |                   | JFMA2G225K275000B → |                         |  |
| B32654A4225J000 |                   | JFMA2G225J275000B → |                         |  |
| B32654A7224K000 |                   | JFMA3B104K275000B → |                         |  |
| B32654A7224J000 |                   | JFMA3B104J275000B → |                         |  |
| B32656S0105K561 |                   |                     | TMCF17-105K1KVP25B →    |  |
| B32922C3154K000 | C42Q2154K6S →     | JFW0A9154K150000B → | TMCF18-154K305VP15      |  |
| B32922C3154M000 | C42Q2154M6S →     | JFW0A9154M150000B → | TMCF18-154M305VP15      |  |
| B32922C3224K000 | C42Q2224K6SC322 → | JFW0A9224K150000B → | TMCF18-224K305VP15 →    |  |
| B32922C3224M000 | C42Q2224K6SC322 → | JFW0A9224M150000B → | TMCF18-224M305VP15 →    |  |
| B32922C3334K000 | C42Q2334K6S →     | JFW0A9334K150000B → | TMCF18-334K305VP15      |  |
| B32922C3334M000 | C42Q2334M6S →     | JFW0A9334M150000B → | TMCF18-334M305VP15      |  |

|                 |                   |                        |                         |                   |
|-----------------|-------------------|------------------------|-------------------------|-------------------|
| B32923C3684M000 | C42Q2684M9S →     | JFW0A9684M225000B →    | TMCF18-684M305VP22.5    |                   |
| B32923C3684K000 | C42Q2684K9S →     | JFW0A9684K225000B →    | TMCF18-684K305VP22.5    |                   |
| B32923C3155M000 | C42Q2155M9S →     | JFW0A9155M225000B →    | TMCF18-155M305VP22.5    |                   |
| B32923C3155K000 | C42Q2155K9S →     | JFW0A9155K225000B →    | TMCF18-155K305VP22.5    |                   |
| B32924C3335M000 | C42Q21335MBS →    | JFW0A9335M275000B →    | TMCF18-335M305VP27.5    |                   |
| B32924C3335K000 | C42Q21335KBS →    | JFW0A9335K275000B →    | TMCF18-335K305VP27.5    |                   |
| B32774D8505K000 |                   |                        | TMCF17-505K800VP27.5B → |                   |
| B32562H3225J000 | C252E225J60 →     |                        |                         |                   |
| B32562H3225K000 | C252E225K60 →     |                        |                         |                   |
| B32562H3225M000 | C252E225M60 →     |                        |                         |                   |
| B32656A7474K000 |                   | JFQ03B474K375000B →    |                         | HSB1200K0.47-EC → |
| B32656A7474J000 |                   | JFQ03B474J375000B →    |                         | HSB1200K0.47-EC → |
| B32656S7105K418 |                   | JF1L3B105K120000B      | TMCF17-105K1250VP28B    |                   |
| B32922C3104M189 |                   | JFW0A9104K150000B01 →  | TMCF18-104K305VP15B →   |                   |
| B32923C3684K000 |                   | JFW0A9684K2250000B01 → | TMCF18-684K305VP22.5B   |                   |
| B32653A6224K000 | C322J224J90C450 → | JFM02J224K225000B →    | TMCF17-224K630VP22.5B → |                   |
| B32653A6224J000 | C322J224J90C450 → | JFM02J224K225000B →    | TMCF17-224K630VP22.5B → |                   |

|                 |                   |                   |                        |  |
|-----------------|-------------------|-------------------|------------------------|--|
| B32022A3222M000 |                   | JFYA2222K10000B → |                        |  |
| B32022A3222K000 |                   | JFYA2222K10000B → |                        |  |
| B32672L8152J000 | C33V1152J60C000 → |                   |                        |  |
| B32021A3103M289 |                   |                   | TMCF29-103K300VP10B    |  |
| B32526R1107K000 |                   |                   | TMCF06-107K100VP37.5B  |  |
| B32652A0104K289 |                   |                   | TMCF17-104K1600VP15B   |  |
| B32656S8335K562 |                   |                   | TMCF17-335K850VP25B    |  |
| B32676E6475K000 |                   |                   | TMCF17-475K630VP37.5B  |  |
| B32653A8223J000 |                   |                   | TMCF17-223K2KVP22.5B   |  |
| B32654A7334K000 |                   |                   | TMCF17-334K1250VP27.5B |  |
| B32656S2224K561 |                   |                   | TMCF17-224K2KVP28B     |  |
| B32656S0225K561 |                   |                   | TMCF17-225K1KVB        |  |
| B32674D1155K000 |                   |                   | TMCF17-155K500VP27.5B  |  |
| B32674D4225K000 |                   |                   | TMCF17-225K450VP27.5B  |  |
| B32674D4475K000 |                   |                   | TMCF17-475K450VP27.5B  |  |
| B32676E4106K    |                   |                   | TMCF17-106K450VP37.5B  |  |
| B32776G8156K    |                   |                   | TMCF17-156K800VP37.5B  |  |
| B32776T1275K000 |                   |                   | TMCF17-275K1300VP37.5B |  |
| B32778G0306K000 |                   |                   | TMCF17-306K1100VP52.5B |  |
| B32912A3104M000 |                   |                   | TMCF18-104K330VP15B    |  |
| B32913A3474K000 |                   |                   | TMCF30-474K330VP22.5B  |  |
| B32924C3475M    |                   |                   | TMCF18-475K305VP27.5B  |  |
| B32926C3225M000 |                   |                   | TMCF18-225K305VP37.5B  |  |
| B81123C1682M    |                   |                   | TMCF30-682K500VP22.5B  |  |
| B32656S7105K418 |                   |                   | TMCF17-105K1250VP28B   |  |

|                 |               |  |                     |                    |
|-----------------|---------------|--|---------------------|--------------------|
| B32922C3104M189 |               |  | TMCF18-104K305VP15B |                    |
| B32912A3154M000 | C44R1154M6S → |  |                     | MKP64/C44R1154M6S  |
| B32912A3154K000 | C44R1154K6S → |  |                     | MKP64/C44R1154K6S  |
| B32912A3473M000 | C44R1473M6S → |  |                     | MKP64/C44R1473M6S  |
| B32912A3473K000 | C44R1473K6S → |  |                     | MKP64/C44R1473K6S  |
| B32913A4104M000 | C45S1104M9S → |  |                     | MKP65/C45S1104M9S  |
| B32913A4104K000 | C45S1104K9S → |  |                     | MKP65/C45S1104K9S  |
| B32912A3224K000 | C44R1224K6S → |  |                     |                    |
| B32912A3224M000 | C44R1224M6S → |  |                     |                    |
| B25631A0157K300 |               |  |                     | DL12-157K2EA45HA → |
| B25631A0227K300 |               |  |                     | DL12-227K2EA45HA → |
| B25631A0287K300 |               |  |                     | DL12-287K2EA45HA → |
| B25631A0157K500 |               |  |                     | DL12-157K2HA45HA → |
| B25631A0227K500 |               |  |                     | DL12-227K2HA45HA → |
| B25631A0287K500 |               |  |                     | DL12-287K2HA45HA → |
| B25631A0107K600 |               |  |                     | DL12-107K2RA45HA → |
| B25631A0157K600 |               |  |                     | DL12-157K2RA45HA → |

|                 |  |  |  |  |
|-----------------|--|--|--|--|
| B25631A0227K600 |  |  |  | DL12-227K2RA45HA    |
| B25631A0666K800 |  |  |  | DL12-666K2KA45HA    |
| B25631A0107K800 |  |  |  | DL12-107K2KA45HA    |
| B25631A0147K800 |  |  |  | DL12-147K2KA45HA    |
| B25631A0227K800 |  |  |  | DL12-227K2KA45HA    |
| B25631A1666K000 |  |  |  | DL12-666K3AA45HA    |
| B25631A1127K000 |  |  |  | DL12-127K3AA45HA    |
| B25631A1147K000 |  |  |  | DL12-147K3AA45HA    |
| B25631A1506K100 |  |  |  | DL12-506K3LA45HA    |
| B25631A1107K100 |  |  |  | DL12-107K3LA45HA    |
| B25631A1157K100 |  |  |  | DL12-157K3LA45HA    |
| B25631B0157K300 |  |  |  | DL12-157K2EA45HA  |
| B25631B0227K300 |  |  |  | DL12-227K2EA45HA  |
| B25631B0287K300 |  |  |  | DL12-287K2EA45HA  |
| B25631B0157K500 |  |  |  | DL12-157K2HA45HA  |
| B25631B0227K500 |  |  |  | DL12-227K2HA45HA  |
| B25631B0287K500 |  |  |  | DL12-287K2HA45HA  |

|                 |  |  |  |  |
|-----------------|--|--|--|--|
| B25631B0107K600 |  |  |  | DL12-107K2RA45HA    |
| B25631B0157K600 |  |  |  | DL12-157K2RA45HA    |
| B25631B0227K600 |  |  |  | DL12-227K2RA45HA    |
| B25631B0666K800 |  |  |  | DL12-666K2KA45HA    |
| B25631B0107K800 |  |  |  | DL12-107K2KA45HA    |
| B25631B0147K800 |  |  |  | DL12-147K2KA45HA    |
| B25631B0227K800 |  |  |  | DL12-227K2KA45HA    |
| B25631B1666K000 |  |  |  | DL12-666K3AA45HA    |
| B25631B1127K000 |  |  |  | DL12-127K3AA45HA    |
| B25631B1147K000 |  |  |  | DL12-147K3AA45HA    |
| B25631B1506K100 |  |  |  | DL12-506K3LA45HA    |
| B25631B1107K100 |  |  |  | DL12-107K3LA45HA  |
| B25631B1157K100 |  |  |  | DL12-157K3LA45HA  |
| B32653A7473K000 |  |  |  | HSB1200K0.047EA   |
| B32653A7683K000 |  |  |  | HSB1200K0.068EA   |
| B32654A7334K000 |  |  |  | HSB1200K0.068EB   |
| B32653A7104K000 |  |  |  | HSB1200K0.1EA     |

|                 |               |                     |  |                        |
|-----------------|---------------|---------------------|--|------------------------|
| B32654A7104K000 |               |                     |  | HSB1200K0.1EB →        |
| B32654A7154K000 |               |                     |  | HSB1200K0.15EB →       |
| B32654A7224K000 |               |                     |  | HSB1200K0.22EB →       |
| B32654A7334K000 |               |                     |  | HSB1200K0.33EB →       |
| B32656A7334K000 |               |                     |  | HSB1200K0.33EC →       |
| B32656A7474K000 |               |                     |  | HSB1200K0.47EC →       |
| B32656A7684K000 |               |                     |  | HSB1200K0.68EC →       |
| B32656A7105K000 |               |                     |  | HSB1200K1.0EC →        |
| B32656A7155K000 |               |                     |  | HSB1200K1.5EC →        |
| B32656A0225K000 |               |                     |  | TMCF17-225K1KVP37.5B → |
| B32652A0103J189 |               |                     |  | TMCF17-103J1KVP15B →   |
| B32652A6104J000 | C322J104J60 → | JFMA2J154J150000B → |  |                        |
| B32652A6224J000 | C322J224J60 → | JFMA2J224J150000B → |  |                        |
| B32652A6334J000 | C322J334J60 → | JFMA2J334J150000B → |  |                        |
| B32652A6394J000 | C322J394J60 → | JFMA2J394J150000B → |  |                        |